

# CERTIFICATE OF APPROPRIATENESS PLACARD

for Raleigh Historic Resources

### 634 N BLOUNT STREET

Address

**BLOUNT STREET** 

**Historic District** 

DR. HAYWOOD HOUSE

**Historic Property** 

114-14-MW

Certificate Number

8/8/2014

Date of Issue

2/8/2015

**Expiration Date** 

This card must be kept pasted in a location within public view until all phases of the described project are complete. The work must conform with the code of the City of Raleigh and laws of the state of North Carolina. When your project is complete, you are required to ask for a final zoning inspection in a historic district area. Telephone the RHDC office at 832-7238 and commission staff will coordinate the inspection with the Inspection, your Certificate of Appropriateness is null and void.

Pro	ort	Descri	nti	nn.
ווע	CCI	Descri	VIII.	VIII.

Remove dangerous 33" dbh Sugar maple tree;plant new Oak tree

Signature,

Raleigh Historic Development Commission

Pending the resolution of appeals, commencement of work is at your own risk.



Development Services
Customer Service Center
One Exchange Plaza
1 Exchange Plaza, Suite 400
Raleigh, North Carolina 27601
Phone 919-996-2495
eFax 919-996-1831

### Raleigh Historic Development Commission - Certificate of Appropriateness (COA) Application

RALEIGH HISTORIC DEVELOPMENT COMMISSION  X Minor Work (staff review) – 1 copy  Major Work (COA Committee review) – 13 copies  Most Major Work Applications  Additions Greater than 25% of Building Square Footage  New Buildings  Demo of Contributing Historic Resource  Post Approval Re-review of Conditions of Approval			<b>3</b>	For Office Use Only  Transaction # 40 4 694  File # 114-14-MW  Fee 200  Amt Paid 200  Check # Rec'd Date 2 4-14  Rec'd By Chride		
•	If completing by hand, please u	se BLACK INK. Do not use blue	e, red, any other color	, or pencil as these do not photocopy.		
Property:	Street Address 634 N. Blount St	reet	-,			
Historic D	District Blount Street					
Historic P	roperty/Landmark name (if app	licable) Dr. Hubert Benbury	Haywood House			
Owner's f	Name Jimmy Thiem & Thyra Ra	uch				
Lot size 0.28 acres (width in feet) 105.0			(depth in feet) 116.4			
For applications that require review by the COA Committee (Major Work), provide addressed, stamped envelopes to owners of all properties within 100 feet (i.e. both sides, in front (across the street), and behind the property) not including the width of public streets or alleys:						
Property Address		Property Address				
48						
I understand that all applications that require review by the commission's Certificate of Appropriateness Committee must be submitted by 4:00 p.m. on the application deadline; otherwise, consideration will be delayed until the following committee meeting. An incomplete application will not be accepted.						

Type or print the follow	ving:				
Applicant Jimmy Thier	m				
Mailing Address 634 N	l. Blount Street				
City Raleigh	State NC Zip Code 27604				
Date 7/30/14	Daytime Phone 919-333-3518				
Email Address jethiem	n@bellsouth.net				
Signature of Applicant	James E	Thian	<u>'M'</u>		
		0.01			
Upon being signed and dated below by the Planning Director or designee, this application becomes the Minor Work Certificate of Appropriateness. It is valid until					
U					
Project Categories (check all that apply):    Exterior Alteration					
Design Guidelines Please cite the applicable sections of the design guidelines (www.rhdc.org).					
Section/Page Topic			Brief Description of Work		
2.3.5/13 Replace diseased tree		Replace Sugar Maple with trunk rot in front yard			
5.2.4/62 Plan: replacement tree		New tree to replace tree removed			
				The state of the s	

TO BE COMPLETED BY APPLICANT						TO BE COMPLETED BY CITY STAFF		
			YES	N/A	YES	NO	N/A	
graphic i be sure y	Attach 8-1/2 " x 11" sheets with written descriptions and drawings, photographs, and other graphic information necessary to completely describe the project. Use the checklist below to be sure your application is complete.  Minor Work (staff review) – 1 copy							
Major W	ork (COA	Committee review) – 13 copies						
1.		description. Describe clearly and in detail the nature of your project. exact dimensions for materials to be used (e.g. width of siding, window.)	х					
2.	Descript	ion of materials (Provide samples, if appropriate)	Х		1			
3.	3. Photographs of existing conditions are required.		Х					
4.	Paint Scl	nedule (if applicable)		Х				
5.	sidewalk includes accurate you bou	(if applicable). A plot plan showing relationship of buildings, additions, is, drives, trees, property lines, etc., must be provided if your project any addition, demolition, fences/walls, or other landscape work. Show measurements. You may also use a copy of the survey you received when ght your property. Revise the copy as needed to show existing conditions proposed work.	х					
6.	Drawings showing proposed work							
	_ _ _	Plan drawings Elevation drawings showing the new façade(s).  Dimensions shown on drawings and/or graphic scale.  8-1/2" x 11" reductions of full-size drawings. If reduced size is so small as to be illegible, make 8-1/2" x 11" snap shots of individual drawings on the	Х					
7.		big sheet.  envelopes addressed to all property owners within 100 feet of property ting the width of public streets and alleys. (Required for Major Work)		х				
8.	8. Fee (See Development Fee Schedule)		Х			/		

# DR. HUBERT BENBURY HAYWOOD HOUSE 634 NORTH BLOUNT STREET, RALEIGH, NC

Date: 7/30/14

Re: Removal of existing tree and replacement with new tree

An existing Sugar Maple (Acer saccharum), 33" d.b.h, in the front yard of the subject property has a large cavity beginning at the base of the tree and extending up into the tree approximately 4.5 feet from ground level. The cavity measures approximately 14 inches in diameter about midway up.

### TREE REMOVAL

Last October, 2014, Hunter Tree Service trimmed various trees around the house in preparation for remedial, in kind, roof work, exterior trim and painting. During their work, Phil Crump, Certified Arborist with Hunter Tree Service, observed the cavity, and noted that the tree was structurally at risk. He recommended it be removed. The tree is in close proximity to the house.

We, wife Thyra and I, have finally, after much discussion, decided to follow Phil's advice, rather than risking possible damage to the house in the future. Removal of the tree is anticipated to occur no later than mid-October, 2014. A report from Phil Crump regarding the trees condition is attached.

### TREE REPLACEMENT

We propose to plant a shade tree to replace the removed Sugar Maple. We propose to plant either a Northern Red Oak (Quercus rubrum) or a Nuttall Oak (Quercus nuttallii). The new tree is to be a minimum of 2" caliper. The approximate location for the new tree is shown on the attached site plan titled "Proposed Tree Removal & Replacement". Installation of the new tree is proposed to occur no sooner than December, 2014, after fall leaf drop, and to be completed no later than id-January, 2015.


## PHOTOS OF SUGAR MAPLE TO BE REMOVED AT 634 NORTH BLOUNT STREET



634 N. Blount Street front yard - Sugar Maple to be removed on right







PR. HUBERT BENBURY HAMWOOD HOUSE 634 N. BLOUDT STREET PROPOSED TREE REMOVAL & REPLICEMENT DOTE: 7/30/14



# HUNTER TREE AND LANDSCAPE COMPANY

Pruning & Removals

Planting & Fertilization

Surgery & Preservation

Landscape Installation

Horticultural Treatments

Appraisals & Diagnosis

Consultation & Design

Irrigation Systems

August 1st, 2014

Jimmy Thiem and Thyra Rauch 634 N. Blount Street Raleigh, NC 27604

RE: structural evaluation of sugar maple tree located in front of 634 Blount Street, Raleigh, NC

Dear Jimmy and Thyra,

A large hollow in the large sugar maple at the front of your residence referenced above attracted my attention while I was working at your residence recently. At your request, I have inspected the tree. We have been watching this defect for a number of years, and at this time I feel it should be addressed.

Measurements of the hollow indicate at least an 18% loss of structural wood tissue in the lower-most segment of the tree trunk. Two additional concerns may exasperate the original issue of the hollow. First is the tree species itself. Sugar maple, as with all maples, is a mediocre compartmentalizer, at best, and as such, does not deal well with containment of disease and decay. More importantly, the hollow is situated directly below the primary union of the two co-dominant leaders (trunks) of this tree.

My judgment and concern is that the decay attributing to the hollow will continue to move upward and weaken this union, potentially causing a catastrophic failure of the tree. Based on this opinion, my recommendation is to strongly consider removal of this tree as soon as your budget will allow.

If I may be of further assistance in this matter, please contact me at your convenience.

With regards,

Philip Hunter Crump

Consultant and practitioner - project arboriculture and landscape horticulture Certified arborist and plantsman

BS (NCSU) Horticulture Science, minors: Forestry Management, Soil Science, Wetland Assessment, and Environmental Science

ALL **ORRESPONDENCE:** 

**21 MARSH AVENUE** RALEIGH NC 27606

> 919-782-7596 919-614-2525

phcrump@gmail.com

NOW OR FORMERLY











