Rł	HDC
	GH HISTORIC

914 W Cabarrus St

Address

Boylan Heights Historic District

Historic Property

COA-0015-2023

Certificate Number

3/6/2023

Date of Issue

9/6/2023 Expiration Date

expiration Date

This card must be kept posted in a location within public view until all phases of the described project are complete. The work must conform with the code of the City of Raleigh and laws of the state of North Carolina. When your project is complete, you are required to ask for a final zoning inspection in a historic district area. Telephone the RHDC office at 832-7238 and commission staff will coordinate the inspection with the inspections Department. If you do not call for this final inspection, your Certificate of Appropriateness is null and void.

Ein Mothon

Raleigh Historic Development Commission

Pending the resolution of appeals, commencement of work is at your own risk.

Signature,

CERTIFICATE OF **A**PPROPRIATENESS **P**LACARD

for Raleigh Historic Resources

Project Description:

Remove existing shed; remove existing wood fence; enclose rear porch; remove and relocate existing rear window and trim; relocate existing rear door; remove non-historic side concrete stair; alter non-historic accessory structure with installation of composite lap siding and new door; install front flagstone pathway; repaint with no change in colors

Type or print the following:				
Applicant name: Lynn Sears (Sears Family LLC)				
Mailing address: P O Box 33483				
City: - Raleigh	State: NC Zip code: 27636			
Date: 2-2-2023	Date: 2-2-2023 Daytime phone #: 919-427-0045			
Email address: lsears@searscontra	ict.com			
Applicant signature:				
Minor work (staff review) – one copy Major work (COA committee review) – ten copies Additions > 25% of building sq. footage New buildings Demolition of building or structure All other Post approval re-review of conditions of		Office Use Only Transaction #: File #: COA-0015-2023 Fee: Amount paid: Received date: Received by:		
approval				
Property street address: 914 W. Cabarrus Street				
Historic district: Boylan Heights				
Historic property/Landmark name	(if applicable):			
Owner name: Sears Family LLC				
Owner mailing address: P O Box 3	3483 Raleigh, NC 2	7636		

For applications that require review by the COA Committee (major work), provide addressed and stamped envelopes for owners for all properties with 100 feet on all sides of the property, as well as the property owner.

Property Owner Name & Address	Property Owner Name & Address	

REVISION 7.2.19

I understand that all major work applications that require review by the Raleigh Historic Development Commission's COA Committee must be submitted by 4 p.m. on the date of the application deadline; otherwise, consideration will be delayed until the following committee meeting. An incomplete application will not be accepted.

Will you be applying for rehabilitation tax credits for this project?	Office Use Only	
Yes No	Type of work: 9, 15, 29, 35, 57, 66, 83,	
Did you consult with staff prior to filing the application?		
Yes No		

Design Guidelines: please cite the applicable sections of the design guidelines (www.rhdc.org).			
Section/Page	Topic	Brief description of work (attach additional sheets as needed).	
		Infill rear porch, remove stair, replace window, replace door on workshop, install siding on workshop	
		Remove existing fence, remove existing shed (no foundation), Install flagstone stepping stones	
		See attached project description	

Minor Work Approval (office use only)

Upon being signed and dated below by the Planning Director or designee, this application becomes the Minor Work Certificate of Appropriateness. It is valid until __09/06/2023_____

Please post the enclosed placard form of the certificate as indicated at the bottom of the card. Issuance of a Minor Work Certificate shall not relieve the applicant, contractor, tenant, or property owner from obtaining any other permit required by City Code or any law. Minor Works are subject to an appeals period of 30 days from the date of approval.

Signature (City of Raleigh) _____ Ma

Date 03/06/2023

Page 2 of 2

REVISION 7.2.19



Rev 1: 2-22-2023

914 W. Cabarrus St. Boylan Heights

Project Description and Description of Materials

Main House:

House is a one-story bungalow with an attached front porch circa 1922 according to the National Register Nomination of Boylan Heights.

1- An existing rear porch not visible to street is proposed to be enclosed with new walls wrapped with **4**" wood siding and 4" corner trim to match existing. No drip cap on foundation exists at rear of house. No drip cap shall be installed at rear enclosed porch. Existing wood floor and brick foundation to remain. Existing concrete stairs to remain. Existing rear half glass wood door at rear of house will be relocated to enclosed mud room rear façade (not a character defining façade). Existing roof and exposed rafter tails to remain. Existing window in rear façade inside existing screen porch to be relocated and will be filled in with siding. *See National Historic Trust for Preservation Brief below.

2-Remove existing non-original concrete stair to the right of front porch. This stair protrudes into driveway and needs to be removed to allow for vehicles to park.

3-Patch and repair parging on foundations. Patch and repair any rotten wood siding or other elements. Repaint all surfaces (colors to be selected at a later date)

4- Relocate rear window to East elevation and replace trim to match original.

Workshop:

5-Install new glass and wood door at existing workshop circa 1988 according to tax records. Install 4" exposure composite smooth faced siding over CMU at workshop. All elements to be painted to match main house.

Site:

6- Remove existing wood fence on either side of house.

7- Install flagstone stepping stones in front yard.

8-Repair existing brick pavers in rear yard.

Massing/Demolition:

9- Remove existing deteriorated potting shed (no existing floor or foundation). Built mass will be reduced with removal of shed.



Cited Design Guidelines:

1.5 Walkways

.4 If a walkway or a driveway is completely missing, replace it with a new feature based on accurate documentation of the original design or a new design compatible in location, configuration, dimension, scale, materials, and color with the historic building site, streets, and district.

.5 Design new walkways, driveways, and off-street parking areas to be compatible in location, patterns, spacing, configurations, dimensions, materials, and color with existing walkways, driveways, and off-street parking areas that contribute to the overall historic character of the district.

1.6 Garages and Accessory Structures:

.7 Select materials and finishes for proposed garages or accessory buildings that are compatible with the principal structure or other historic garages and accessory buildings in the district in terms of composition, scale, module, pattern, detail, texture, finish, color, and sheen.

.8 Select windows and doors for new garages and accessory buildings that are compatible in material, subdivision, proportion, pattern, and detail with the windows and doors of the principal structure or other historic garages and accessory buildings in the district.

2.7 Windows and Doors:

.6 If a historic window or door unit is deteriorated beyond repair, replace the unit in kind, matching the design and the dimension of the original sash or panels, pane configuration, architectural trim, detailing, and materials. Consider compatible substitute materials only if using the original material is not technically feasible.
.9 If additional windows or doors are necessary for a new use, install them on a rear or non-character-defining facade of the building, but only if they do not compromise the architectural integrity of the building.
.11 It is not appropriate to remove original doors, windows, shutters, blinds, hardware, and trim from a character-defining facade.

2.8 Entrances, Porches, and Balconies:

.7 Consider the enclosure of a historic porch to accommodate a new use only if the enclosure can be designed to preserve the historic character of the porch and the building. It is not appropriate to enclose a front porch or a front balcony.

3.2 Additions:

.6 Locate a new addition on an inconspicuous face of the historic building, usually the rear one.

*Reference:

National Park Service Preservation Briefs: #45 Preserving Historic Wood Porches

Regarding enclosure of porches, the text states: ...

"History has shown that the enclosure of a portion of a porch on a secondary elevation does not always alter the character of a building. In the past as indoor plumbing was introduced to old buildings, the partial enclosure of a one or two-story porch on a secondary elevation was a convenient means of providing new bathroom space while limiting disruption to the building's interior. ... This also provides us with an approach that may be appropriate for a particular project today."

"Unless the historic porch is so deteriorated that it is beyond repair, any consideration of enclosing all or part of a porch should incorporate retention of historic fabric. This may mean that the existing structural system needs to be augmented but generally not replaced."



914 W CABARRUS EXISTING CONDITIONS PHOTOS

STREETSCAPE-FRONT ELEVATION



LEFT-FRONT ELEVATION



RIGHT-FRONT ELEVATION - VIEW FROM STREET



CONCRETE STAIRS TO BE REMOVED



RIGHT ELEVATION, VIEW OF EXISTING FENCE, SHED, WORKSHOP



VIEW OF WINDOW TO BE REPLACED ON RIGHT ELEVATION



REAR ELEVATION- EXISTING SCREEN PORCH TO BE INFILLED



ALTERNATE VIEW OF SCREEN PORCH FROM NEIGHBORS YARD



EXAMPLE OF ROTTEN DRIP CAP/SIDING TO BE REPLACED IN KIND



VIEW OF WORKSHOP FRONT ELEVATION, POTTING SHED, EXISTING SCREEN PORCH ON LEFT



VIEW FROM INSIDE SCREEN PORCH LOOKING AT REAR WORKSHOP



RIGHT SIDE ELEVATION OF WORKSHOP FROM NEIGHBORS YARD



VIEW REAR YARD, 6'4"H EXISTING FENCE, LEFT ELEVATION WORKSHOP



BRICK PATIO IN REAR YARD TO BE REPAIRED



EXISTING FENCE ON LEFT SIDE

PRECEDENTS OF ENCLOSED PORCHES WITH SIDING - BOYLAN HEIGHTS



PRECEDENT OF APPROVED ENCLOSED FRONT PORCH (COA-146-17-MW AND COA-142-17 MW)


317 S. Boylan Before





FRONT

317 S. Boylan After Enclosure of Side Porches ${\tt I}$











NOTE:


PATCH AND REPAIR ANY DAMAGED SIDING, TRIM, PARGING OR OTHER EXTERIOR ELEMENTS AS REQUIRED AT ALL EXTERIOR ELEVATIONS, TYP.





1-31-2023


ELEVATIONS


PROPOSED










































914 W. Cabarrus WORKSHOP

MARVIN'®
ORDERING PRODUCTS WITH REFERENCE TO SHOP DRAWINGS: Before ordering the Marvin products illustrated within these shop drawings, a copy of these drawings accompanied by an approved signature of the purchaser must be returned to the Architectural Division at Marvin Windows & Doors, P.O. Box 100, Warroad, Minnesota 56763. If the Marvin products included herein are ordered without reference to the approved shop drawings, Marvin Windows and Doors assumes no responsibility in guaranteeing product coordination with the drawings.
PROJ/JOB: Maurer Architecture / B Tate - Historic Replacement Door DIST/DEALER: MARVIN WINDOWS AND DOORS DRAWN: CHERYL MCRAE QUOTE#: QFC475M PK VER:0003.18.00 CREATED:01/31/2023REVISION:
SHEET 1
OF 1



Inswing Section Details: Raised Panel Placement

Scale: 3" = 1' 0"



NOTE: Illustrated with 1 3/4" panels, but also available with 2 1/4" panel product. Available with IZ3.



914 W. Cabarrus WORKSHOP