

CERTIFICATE OF APPROPRIATENESS PLACARD

for Raleigh Historic Resources

Project Description:

Replace front porch and kitchen roof coverings

513 Polk St

Address

Oakwood

Historic District

Historic Property

COA-0022-2020

Certificate Number

2/24/2020

Date of Issue

8/24/2020

Expiration Date

This card must be kept posted in a location within public view until all phases of the described project are complete. The work must conform with the code of the City of Raleigh and laws of the state of North Carolina. When your project is complete, you are required to ask for a final zoning inspection in a historic district area. Telephone the RHDC office at 832-7238 and commission staff will coordinate the inspection with the inspections Department. If you do not call for this final inspection, your Certificate of Appropriateness is null and void.

Signature,

Collette R Kurnie

Raleigh Historic Development Commission

Pending the resolution of appeals, commencement of work is at your own risk.

	Type or print th	e following:		
Applicant name: John Clay				
Mailing address: 513 Polk St	treet			
City:Raleigh	State:NC		Zip code:27604	
Date:2/5/2020		aytime phone	aytime phone #:919-624-2594	
Email address:for.jclay@gm				
Applicant signature:	hu & . Cay	y en		
Minor work (staff review) – one copy			Office Use Only	
Major work (COA committee review) - ten		3.2 (a) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c	Transaction #:	
copies		File #: <u>COA - 00 22 - 20</u> 20		
Additions > 25% of building sq. footage		Fee:		
New buildings		Amount paid:		
Demolition of building or structure		Received date:		
All other		Received by:		
Post approval re-review of conditions of				
approval				
Property street address:513 F	Polk Street, Raleigh,	NC 27604		
Historic district: Oakwood		***		
Historic property/Landmark na	me (if applicable):			
Owner name: John Clay				
Owner mailing address: same				
	owners for all propert		jor work), provide addressed et on all sides of the property,	
Property Owner Name	& Address	Propert	y Owner Name & Address	
	表示: 1 - 1 · 1 · 1 · 1 · 1 · 1			
		entere District		
	STORY TO STORY			

I understand that all major work applications that require review by the Raleigh Historic Development Commission's COA Committee must be submitted by 4 p.m. on the date of the application deadline; otherwise, consideration will be delayed until the following committee meeting. An incomplete application will not be accepted.

Yes No	plying for rehabilitati	on tax credits for this project? ling the application?	Type of work: 100
Design	Guidelines: please ci	e the applicable sections of the d	esign guidelines (www.rhdc.org).
Section/Page	Topic	Brief description of work (attach additional sheets as needed).	
2.5/46 Roofs		see attached	
Certificate of App Please post the e Certificate shall n	d and dated below by the ropriateness. It is valid unclosed placard form of ot relieve the applicant, law. Minor Works are su	the certificate as indicated at the bot contractor, tenant, or property owner bject to an appeals period of 30 day	tom of the card. Issuance of a Minor Work from obtaining any other permit required by a from the date of approval.
Signature (City of	Raleigh) Coccur	ti R L	Date 02/14/10

513 Polk Street, Raleigh, NC 27604 - Historic Oakwood


<u>Kitchen:</u> According to previous owners, the kitchen was expanded and renovated in the mid-1990s. At the time, an asphalt roof covered the new section and a terne standing seam roof covered the original back porch which became the front half of the kitchen. Now - asphalt shingles are failing and the skylights from 1990s addition are leaking. The older standing seam section is 8 feet X 33.5 feet. The newer asphalt section with skylights is 8.5 feet X 23.5 feet needs to be replaced.

<u>Kitchen Request:</u> replace the asphalt shingles with copper with 1 inch standing seam and 17 inch panels to match terne metal of remainder of the roof. According to research and comments by Christian Ninino, roofer, Follansbee is out of business so terne roofing supplies are not available. Replacement stainless steel is more expensive than copper. There are many copper roofs on houses of same era in Oakwood.

<u>Front porch</u>: Asphalt shingles are same age as the kitchen shingles. No leaks yet. According to Dean Reudriche, whose sister lived in my house when it was a duplex in the 1960's, the front porch roof at that time was standing seam terne – so I would like to return it to the same form even if it is a different material. This roof can be visualized as a single surface with two sections: 7 feet X 7.5 feet and 7 feet X 17 feet in the .

<u>Front porch Request:</u> replace the front porch roof with copper with 1 inch standing seams and 17 inch panels to match the kitchen.

If these two projects are completed, then all roofs will be slate, flat seam or standing seam.



Clay - 513 Polk Street, Raleigh NC 27604 - 919-624-2584

1. Kitchen – west facing; standing seam; skylights and asphalt



2. Kitchen – west facing; asphalt and skylights



3. Kitchen – east facing; standing seam; skylights and asphalt



4. Frontporch – south facing – longest dimension



5. Frontporch – west facing – shortest dimension

