

# APPLICATION FOR A CERTIFICATE OF APPROPRIATENESS – STAFF REPORT

COA-0033-2019 308 S BOYLAN AVENUE

Applicant: LAURIE JACKSON

Received: 3/13/19 Meeting Date(s):

<u>Submission date + 90 days</u>: 06/11/19 1) 04/25/2019 2) 3)

## **INTRODUCTION TO THE APPLICATION**

<u>Historic District</u>: BOYLAN HEIGHTS HISTORIC DISTRICT Raleigh Historic Landmark: THE BOYLAN MANSION

Zoning: HOD-G

Nature of Project: Construct rear addition; install wheelchair lift; alter balcony railing; install

new balconies; replace columns

<u>DRAC</u>: An application was reviewed by the Design Review Advisory Committee at the April 1, 2019 meeting. Members in attendance were Jenny Harper, Mary Ruffin Hanbury, and Sarah David; also present were Laurie Jackson and David Maurer, architects; Sara and Jeff Shepherd, property owners; and Collette Kinane and Tania Tully, staff.

### Staff Notes:

• COA cases mentioned are available for review.

### APPLICABLE SECTIONS OF GUIDELINES and DESCRIPTION OF PROJECT

<u>Sections</u>	<u>Topic</u>	<u>Description of Work</u>
1.3	Site Features and Plantings	Construct an addition;
2.8	Entrances, Porches, &	Replace a balcony railing; install new balconies;
	Balconies	replace columns
2.11	Accessibility, Health, & Safety	Install a wheelchair lift
3.2	Additions	Construct an addition; install a wheelchair lift

# **STAFF REPORT**

Based on the information contained in the application and staff's evaluation:

- A. Constructing an addition; installing a wheelchair lift; replacing a railing; installing new balconies; and replacing columns are not incongruous in concept according to *Guidelines* 1.3.1, 1.3.2, 1.3.6, 1.3.7, 1.3.8, 1.3.9, 2.8.1, 2.8.5, 2.8.6, 2.8.10, 2.11.1, 2.11.2, 2.11.3, 2.11.5, 2.11.8, 3.2.2, 3.2.4, 3.2.5, 3.2.6, 3.2.7, 3.2.8, 3.2.9, 3.2.11, 3.2.12; and the following suggested facts:
- 1\* The National Register of Historic Places nomination for Montfort Hall describes the relationship of the house to its site as: "The siting of Montfort Hall is still impressive, for it stands amid a one-acre plot of land on the highest elevation for some distance around.

- From this vantage point, once located in a semi-rural area but now surrounded by early twentieth century development, Montfort Hall overlooks the immediate neighborhood of Boylan Heights...This siting recalls Montfort Hall's proud role as one of a series of luxurious suburban mansions built shortly before the Civil War for Raleigh's wealthy families."
- 2\* A previous approved application (COA-0013-2019) included the removal of trees, removal of a portion of fence in the rear yard, reconstruction of the chimneys, and the installation of walkways and parking areas.
- 3\* The application proposes the construction of a second story rear addition on top of an existing addition. A new two-story stair tower and covered entry with wheelchair lift will replace an existing wooden stair and lift. Lift details were not provided.
- 4\* The addition will be clad in wood siding to match the existing addition on the south facade. It features a low slope roof that meets the historic structure below the decorative entablature.
- 5\* The rear is a traditional location to add onto a house.
- 6\* The eave is proposed to match the existing on the south addition. Neither detailed drawings nor close-up photos of the existing eave were provided.
- 7\* The proposed fenestration of the addition matches the rhythm and proportion of the historic house. Window specifications were provided. Trim and casings are proposed to match existing on south addition. Detailed photos were not provided.
- 8\* The application includes the following built **area** to open space analysis: The lot is 43,623 SF. The existing built area is 5,560 SF, or 13%. The approved built area (which includes the walkways, parking areas, and site changes from COA-0013-2019) is 9,279 SF, or 21%. The addition proposed in this application adds 502 SF to create a built area of 9,781 SF, or 22%. This is an increase in built area of 9% total.
- 9\* The application does not distinguish between built mass and built area. However, the proposed first floor plan and side elevation drawings illustrate the diminutive size of the proposed new stair tower in comparison with the historic house.
- 10\* The applicant provided photographs of other rear additions to properties in Boylan Heights.
- 11\* The application proposes the repair of the Juliet balcony on the east façade. The existing railing is proposed to be removed and replaced with a decorative railing that is based on the railings present on The Barracks, a property in Tarboro designed by the same architect.

- 12\* A new Juliet balcony is proposed for the north elevation. This balcony is based on documentation of the property from 1967 that indicates a balcony previously existed in the same location. Detailed drawings were not provided.
- 13\* A walk-out balcony with a new French door is proposed for the west façade on the previous addition. Detail drawings were not provided.
- 14\* The application also proposes the restoration of the columns on the north and south porches. The extant columns are non-historic PVC piping with concrete bases. The applicant proposes replacement with 10" wood columns, capitals, and bases.

15\* Details were not provided for the following proposed changes:

- a. new entry doors for the rear entry.
- b. new painted steel handrail and guardrail for the front entryway and porches
- c. decorative steel security gate for the west façade.

16\* Phase 1 of the tree protection plan was provided.

Staff suggests the committee approve the application with the following conditions:

- 1. That a tree protection plan be implemented and remain in place for the duration of construction.
- 2. That details and specifications for the following be provided to and approved by staff prior to construction or installation:
  - a. Balcony railing details;
  - b. New Juliet balcony detail drawings;
  - c. Walk-out balcony detail drawings;
  - d. Detail photos of trim and casings to be matched;
  - e. Wheelchair lift specifications;
  - f. Painted steel handrail and guardrail specifications;
  - g. Decorative security gate specifications;
  - h. French door specifications and section;
  - i. Rear entry door specifications and section;
  - j. Eave details.

<u>Staff Contact</u>: Collette Kinane, collette.kinane@raleighnc.gov

# **Certificate of Appropriateness | Application**



Development Services Customer Service Center • One Exchange Plaza, Suite 400 | Raleigh, NC 27601 | 919-996-2495

This form can be submitted in person or via USPS at the above address.

	Type or print the	ne following:	
Applicant name:			
Mailing address:			
City:	State:		Zip code:
Date:		Daytime phone	e #:
Email address:			
Applicant signature:			
Minor work (staff roviow) or	oo oony		Office Hee Only
Minor work (staff review) – or		Transaction	Office Use Only
Major work (COA committee	,		on #:
(10 copies will be required after initi	•	File #:	
Additions > 25% of bui	lding sq. footage	Fee:	
New buildings		Amount pa	aid:
Demolition of building	or structure	Received	date:
All other		Received	by:
Post approval re-review of co	nditions of		
approval			
Property street address:			
Historic district:			
Historic property/Landmark name	(if applicable):		
Owner name:			
Owner mailing address:			

Page **1** of **3** REVISION 02.12.19

and stampe				e (major work), provide addressed 100 feet on all sides of the property,
Prop	perty Owner Name &	Address	Pr	operty Owner Name & Address
Developm	ent Commission's on deadline; otherw	COA Committee rise, consideration	nust be su I will be de	ire review by the Raleigh Historic bmitted by 4 p.m. on the date of the layed until the following committee I not be accepted.
project?	applying for rehabilita Yes No sult with staff prior to			Office Use Only Type of work:
Yes No	sait with stail phor to	ming the application	711:	
Dosi	ian Guidolinos: ploaso	cito the applicable so	ctions of the	design guidelines (www.rhdc.org).
Section/Page	Topic			(attach additional sheets as needed).
. 3	'		<u>'</u>	,
Certificate of A	ppropriateness. It is valid	l until	or designee, tl	his application becomes the Minor Work
Certificate shal	I not relieve the applican	t, contractor, tenant, or	property own	pottom of the card. Issuance of a Minor Work her from obtaining any other permit required by ays from the date of approval.
Signature (City	of Raleigh)			Date

Page **2** of **3** REVISION 02.12.19

To be completed by applicant			Office Use Only			
	Yes	N/A	Yes	No	N/A	
Attach 8-1/2"x11" or 11"x17" sheets with written descriptions and drawings, photographs, and other graphic information necessary to completely describe the project. Use the checklist below to be sure your application is complete.  Minor Work (staff review) – 1 copy  Major Work (COA Committee review) – 1 copy (10 copies will be required after initial staff review).						
<ol> <li>Written description. Describe clearly and in detail the nature of your project. Include exact dimensions for materials to be used (e.g. width of siding, windown trim, tree species, etc.)</li> </ol>						
2. <b>Description of materials</b> (Provide samples, if appropriate)						
<ol> <li>Color Photographs of existing conditions are required. Minimum image size 4" of as printed. Maximum 2 images per page. Photos should be of each side of the house, fully show the yards, and include streetscapes.</li> </ol>						
4. Paint Schedule (if applicable)						
<ul> <li>5. Site Drawings. Required for projects that include any addition, demolition, fences, walls, or other landscape work.</li> <li>Plot plan   showing relationship of buildings, additions, sidewalks, drives, trees, property lines, etc.</li> <li>Tree survey   include size, species, and critical root zone for each tree over 8" diameter when measured 4' above ground level</li> <li>Tree protection plan   include material staging area, construction access limits of disturbance, location of tree protection fencing</li> <li>Grading plan</li> <li>Dimensions shown on drawings and/or graphic scale (required)</li> <li>11"x17" or 8-1/2"x11" reductions of full-size drawings</li> </ul>						
<ul> <li>6. Architectural Drawings showing existing and proposed work (if applicable)</li> <li>Plan drawings</li> <li>Elevation drawings showing the façade(s). For additions, deck, ar porches, include the grade.</li> <li>Dimensions shown on drawings and/or graphic scale (required)</li> <li>11" x 17" or 8-1/2" x 11" reductions of full-size drawings. If reduced size is so small as to be illegible, make 11" x 17" or 8-1/2" x 11" snap show of individual drawings from the big sheet.</li> <li>7. Stamped envelopes addressed to all property owners within 100 feet of</li> </ul>	ze					
property, on all sides of the property, as well as the property owner (required for Major Work). Use the <u>Label Creator</u> to determine the addresses.						
8. Fee (See Development Fee Schedule)						

Page 3 of 3 REVISION 02.12.19

1703375717 MH BOYLAN LLC 308 S BOYLAN AVE RALEIGH NC 27603-1908 1703373634 MARSCHALL, DAVID J 315 CUTLER ST RALEIGH NC 27603-1919 1703373648 LEE, RICHARD EUGENE 311 CUTLER ST RALEIGH NC 27603-1919

1703373882

1703373754 SHACKLETON, SCOTT P PO BOX 28123 RALEIGH NC 27611-8123 1703373767 FUTORANSKY, DONNA 307 CUTLER ST RALEIGH NC 27603-1919

ROWE, MATTHEW ROWE, TRACI 305 CUTLER ST RALEIGH NC 27603-1919

1703373899 CAMPBELL, KEVIN S 2805 NC 97 HWY WENDELL NC 27591-6986 1703374566 ZAYTOUN REALTY GROUP LLC 320 S BOYLAN AVE STE A RALEIGH NC 27603-1908 1703374673 WHELAN, ANDREW EDWARD KREMER, DARLA J 316 S BOYLAN AVER RALEIGH NC 27603

1703374838 WILKINS, CHARLES P JR 626 W JONES ST RALEIGH NC 27603-1575 1703375997 MOUNTFORD AVENUE ASSOCIATES 706 MOUNTFORD ST RALEIGH NC 27603-1944 1703376583 ZAYTOUN, ADAM MABE ZAYTOUN, SARAH JENSEN 317 S BOYLAN AVE RALEIGH NC 27603-1907

1703377518 WOOSTER, ANDREW WOOSTER, DONNA 315 S BOYLAN AVE RALEIGH NC 27603-1907 1703377648 WARD, CAITLIN HARTWELL 521 W CABARRUS ST RALEIGH NC 27603-1911 1703377911
WAZEE PROPERTIES LLC
C/O RILEY LEWIS GENERAL
CONTRACTORS
PO BOX 6481
RALEIGH NC 27628-6481



Montfort Hall 308 S. Boylan Ave, Raleigh

April 25, 2019

### Summary of Work:

The project scope includes the removal of roof, rotted siding and windows in existing addition on south elevation and the removal of a non-original rear deck, stair and wheelchair lift on the west elevation. The existing brick foundation of the south addition will remain. A new second-story addition will be constructed on the existing, one-story rear portion of the building, and a two-story addition with entry porch and stair will be constructed on the back or west elevation. A new wheelchair lift will also be installed at the new entry porch. The existing addition will be re-clad in wood siding to match the original, and new windows, a new double leaf door and a new roof will be installed on the existing addition. A small, walk-out balcony will be constructed at the west elevation of the existing addition.

The existing juliete balcony on the east elevation will be repaired and the non-original railing removed. A new railing will be installed, based on railing details from The Barracks in Tarboro. The Barracks is a historic plantation house built by the same architect at the same time as Montfort Hall. Per the National Register nomination, Montfort Hall is closely related to the Barracks, designed in 1858 by William Percival. The massing, use of classical and Italianate detail and interior plan are similar. Several decorative features, such as the louvered interior shutters, coved ceilings and the stained glass oculus, are found in both houses. This page from the NR nomination is included for reference, as well as photographs from The Barracks showing the existing historic railing at that location. Finally, an original juliete balcony on the north elevation will be reconstructed and a new railing matching the historic detailing installed. The juliete balcony is shown in this location in the 1967 documentation of Montfort Hall found in the Special Collections Research Center at NCSU libraries. The north elevation drawing from this documentation set is included, showing the location of the juliet balcony on the north elevation.

The north and south porches on the east elevation are undergoing repair prior to the installation of new roofing. When the existing columns were removed, it was discovered that they were later replacements along with the cast capitals and bases. The column material itself is PVC piping. Both porches have a concrete slab topping that is not original, and it appears that the replacement columns were constructed at the same time. The column bases were clearly cast into the slab topping and evidence of 6x6 wood supports within the column were observed. It is proposed to replace the non-original PVC columns and concrete capitals & bases with new, 10" wood columns with a similar 'Temple of the Winds' Corinthian capital and base. Photographs of the existing conditions are included, along with updated site conditions photographs.

Per CoA 0013-2019, the following has already been approved by the Certificate of Appropriateness Committee:

- -Alter driveway and replace curb cut
- -Remove 15 trees, portions of existing fence, construct parking area
- -Replace masonry chimneys, install metal roof



Additions (Section 3.2): The existing fascia of the one-story portion of the building will remain in order to differentiate the second-story addition from the original construction. There will be a low metal roof on the second story addition and the rear addition. The rear addition on the west elevation is inset several feet from the body of the main house on both sides. The rear porch and stair will be built in the same location as the existing porch and stair. The size and scale of the additions are limited so as not to visually overpower the historic building.

<u>Exterior finishes (Sections 2.1-2.2):</u> The new addition will be clad in wood lap siding to match the existing siding. All trim details will match the existing wood trim on the south addition. The foundation wall of the new addition will be brick matching the existing brick foundation on the south addition.

<u>Windows (Section 2.7):</u> The existing windows on the addition will be removed and replaced with new wood windows in the same location. In the new additions, new wood windows will be installed. All new windows shall be Marvin Ultimate Double Hung with putty profile. *Attached are the elevations and head, jamb, and sill details for review.* 

<u>Doors (Section 2.7)</u>: A new custom wood door with 1/4 glass shall be installed at the rear entry porch. A double leaf, full-lite wood door shall be installed on the west side of the existing south addition. All new exterior doors shall be TruStile Reserve wood doors with insulated glass.

Roofing (Section 2.5): The low hip roof of the second story addition and the rear addition will be copper standing seam with 15" wide panels and 1" high ribs with no hip or ridge caps.


Rear Porch (Section 2.8): The new porch and stair on the west elevation will have wood tongue and groove flooring on wood joists. Columns are to be 10" wood with a simple capital and base. The ceiling of the porch will be beaded board. The guard and handrail at the new stair will be wood; details are provided.

### **Built Mass**

The existing built area is 5,660 SF, which is 13% of the 43,623 SF site. The approved built area is 9,279 SF or 21% of the site. The approved built area consists of site circulation features and new parking areas. The proposed built area includes the new two-story stair tower addition, entry porch and stair and walk-out balcony on the west elevation. (The second story addition on the existing one story portion of the building is within the existing building footprint and is not included in the proposed built area calculation.) A site diagram showing the existing, approved and proposed built area is included.


### Fact

Rear two-story additions have been approved in the Boylan Heights Historic District, and photographs are included of 1022 South St., 917 South St., 1100 W. Cabarrus and 511 Cutler St.



EXISTING	TO PROPOSED BUILT AREAS	SF	% OF 43,623 SF SITE
	EXISTING BUILT AREA	5660	13%
***	APPROVED BUILT AREA	9279	21%
	PROPOSED BUILT AREA	502	1 %





# MONTFORT HALL , 308 S BOYLAN AVE TREE PROTECTION PLAN PHASE 1 SCALE : $\frac{1}{32}$ " = 1'-0"



01- Existing east or main elevation



02 - Existing northeast corner of building



03- Existing north elevation



04 - Existing northwest corner of building



05- Existing west elevation



 ${\bf 06}$  - Existing partial south elevation



07- Existing partial south elevation





09- North porch during roof repair. Column base still attached to concrete slab at porch floor



10 - North porch concrete slab showing cast in place base around 6x6 wood post



11- North porch column base and slab with wood band board below



12 - 'Temple of the Wind' column capital cast around PVC column



13- 'Temple of the Wind' column capital cast around PVC column



14 - 'Temple of the Wind' column capital cast around PVC column



15- Existing, historic juliet balcony railing taken at The Barracks, Tarboro NC



16- Existing, historic juliet balcony railing detail taken at The Barracks, Tarboro NC



The Barracks, Tarboro NC

Form No. 10-300a (Rev. 10-74)

# UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

FOR NPS USE ONLY	
RECEIVED	

DATE ENTERED


# NATIONAL REGISTER OF HISTORIC PLACES INVENTORY -- NOMINATION FORM

CONTINUATION SHEET	ITEM NUMBER	7	PAGE	2

however, the second floor gallery has been filled in. The south side of the house, which Mrs. Cox described as the music room, library, master bedroom and bath, has been altered to accommodate the church auditorium. Aside from this renovation, the spaces have been basically maintained. The dining room and parlor contain the original crown moldings and sliding doors, and the stair is intact. None of the original bathrooms or first floor marble mantels, however, remain.

Montford Hall is closely related to The Barracks, designed in 1858 by William Percival for William S. Battle of Tarboro, North Carolina. The massing, use of classical and Italianate detail, and interior plan are similar. Several decorative features, such as louvered interior shutters, coved ceilings, and the stained glass oculus, are found in both houses.

<sup>\*</sup>Excerpt from Montfort Hall National Register nomination with reference to The Barracks



MONTFORT HALL

North Elevation, 1967

Special Collections Research Center at NCSU libraries




917 South St., Boylan Heights

1022 South St., Boylan Heights



Rear, two story additions in the Boylan Heights Historic District



511 Cutler St., Boylan Heights

1100 W Cabarrus St., Boylan Heights



Rear, two story additions in the Boylan Heights Historic District

# WOOD ULTIMATE DOUBLE HUNG WITH PUTTY PROFILE

SECTION DETAILS - OPERATING DOUBLE HUNG SCALE: 1=1

6 9/16"

**HEAD** 



**CHECKRAIL** 



SILL



JAMB






**VERTICAL** 







Mulling information (Double-click to highlight & copy/paste to browser search window): https://www.marvin.com/WebDoc/Marvin%20ADM%20Mulls%20All.pdf Interior Trim Provided for mulls up to 2"






### WOOD ULTIMATE DOUBLE HUNG MO (mm) 2-01/2 (622) 2-41/2 (724) 2-8 1/2 (826) 2-10 1/2 (876) 3-01/2 (927) 3-21/2 (978) 3-41/2 (1029) 3-81/2 (1130) 4-01/2 (1232) RO (mm) FS (mm) 1-10 3/8 (568) 1-9 3/8 (543) 2-23/8 (670) 2-13/8 (645) 2-6 3/8 (772) 2-5 3/8 (746) 2-8 3/8 (822) 2-7 3/8 (797) 2-10 3/8 (873) 2-9 3/8 (848) 3-0 3/8 (924) 2-11 3/8 (899) 3-23/8 (975) 3-13/8 (949) 3-6 3/8 (1076) 3-5 3/8 (1051) 3-10 3/8 (1178) 3-9 3/8 (1153) DLO (mm) 1-215/16 (379) 1-615/16 (481) 1-10 15/16 (583) 2-015/16 (633) 2-215/16 (684) 2-415/16 (735) 2-6 15/16 (786) 2-10 15/16 (887) 3-215/16 (989) 5-10 9/16 (1792) 5-9 1/2 (1765) 5-9 (1753) 2-4 15/16 (735) WUDH4030 E WUDH2430 WUDH2630 WUDH2830 E WUDH3030 E WUDH3230 E WUDH3630 E WUDH1630 WUDH2030 6-2 9/16 (1894) 6-11/2 (1867) 6-1 (1854) 2-6 15/16 (786) WUDH1632 WUDH2032 WUDH2432 WUDH2632 E WUDH2832 E WUDH3032 E WUDH3232 E WUDH3632E WUDH4032 F 6-6 9/16 (1996) 6-5 1/2 (1969) 6-5 (1956) 2-8 15/16 (837) WUDH4034 E WUDH1634 WUDH2034 WUDH2434E WUDH2634E WUDH2834E WUDH3034 E WUDH3234 E WUDH3634 E 6-10 9/16 (2097) 6-9 1/2 (2070) 6-9 (2057) 2-1015/16 (887) WUDH1636 WUDH2036 WUDH2436 E WUDH2636 E WUDH2836 E WUDH3036E WUDH3236E WUDH3636E WUDH4036 E 7-6 9/16 (2300) 7-5 1/2 (22/3) 7-5 (2261) 3-2 15/16 (989) WUDH2440 E WUDH4040 E WUDH1640 WUDH2040 WUDH2640 F WUDH2840 F WUDH3040 F WUDH3240 F WUDH3640 F 7-10 9/16 (2402) 7-9 1/2 (2375) 7-9 (2362) 3-4 15/16 (1040) WUDH1642 WUDH2042 WUDH2442 E WUDH2642E WUDH2842 E WUDH3042 E WUDH3242 E WUDH3642E WUDH4042 E COTTAGE STYLE\* MO (mm) 2-01/2(622) 2-41/2 (724) 2-8 1/2 (826) 2-10 1/2 (876) 3-01/2 (927) 3-21/2 (978) 3-41/2 (1029) 3-81/2 (1130) 4-01/2 (1232) 3-0 3/8 (924) 2-11 3/8 (899) 3-10 3/8 (1178) 3-9 3/8 (1153) RO (mm) 1-10 3/8 (568) 2-2 3/8 (670) 2-63/8(772) 2-8 3/8 (822) 2-10 3/8 (873) 3-23/8 (975) 3-6 3/8 (1076) 2-5 3/8 (746) FS (mm) 1-9 3/8 (543) 2-13/8 (645) 2-73/8 (797) 2-93/8 (848) 3-13/8 (949) 3-5 3/8 (1051) DLO (mm) 1-2 15/16 (379) 1-615/16 (481) 1-10 15/16 (583) 2-0 15/16 (633) 2-215/16 (684) 2-415/16 (735) 2-615/16(786) 2-10 15/16 (887) 3-215/16 (989) 5-10 9/16 (1792) 5-9 1/2 (1765) 5-9 (1753) 1-10 15/16 (583) / 2-10 15/16 (887) WUDH1624/36 WUDH2024/36 WUDH2424/36 WUDH2624/36 WUDH2824/36 WUDH3024/36 WUDH3224/36 WUDH3624/36 WUDH4024/36








Proposed Second Floor Plan






Boylan Avenue Elevation (East)




# **Montfort Hall**






Montfort Street Elevation (North)



# Montfort Hall





Enlarged view of proposed guardrail detail

not to scale

# Montfort Hall






# Montfort Hall





Existing Boylan Avenue Elevation (East)

1/8" = 1'-0"



# **Montfort Hall**





Existing Montfort Street Elevation (North)

1/8" = 1'-0"







Existing Rear Elevation (West)

1/8" = 1'-0"

Montfort Hall





# Montfort Hall

