

601 E Lane St

Address

Oakwood

Historic District

Historic Property

COA-0150-2021

Certificate Number

2/17/2022

Date of Issue

8/17/2022*

Expiration Date

CERTIFICATE OF APPROPRIATENESS PLACARD

for Raleigh Historic Resources

Project Description:

Install new windows; alter front steps; repair front walk in kind

*Beyond this expiration date, NC Session Law 2021-03 grants an extension to all valid development permits until 150-days after NC Executive Order 116 is rescinded.

This card must be kept posted in a location within public view until all phases of the described project are complete. The work must conform with the code of the City of Raleigh and laws of the state of North Carolina. When your project is complete, you are required to ask for a final zoning inspection in a historic district area. Telephone the RHDC office at 832-7238 and commission staff will coordinate the inspection with the inspections Department. If you do not call for this final inspection, your Certificate of Appropriateness is null and void.

Signature,

Ein Morton

Raleigh Historic Development Commission

Pending the resolution of appeals, commencement of work is at your own risk.

Type or print the following:					
Applicant name: Robin & Kimberly Weitkamp					
Mailing address: 601 E. Lane St.					
^{City:} Raleigh	State: NC		Zip code: 27601		
Date: 12 February 2022	Date: 12 February 2022 Da		one #: 408 931 1344		
Email address: robin.weitkamp@gmail.com					
Applicant signature:	UA				
7 -	/				
Minor work (staff review) – one copy			Office Use Only		
Major work (COA committee review) – ten			Transaction #:		
copies		File #: _	File #: COA-0150-2021		
Additions > 25% of building sq. footage		e Fee:	Fee:		
New buildings		Amount	Amount paid:		
Demolition of building or structure		Receive	Received date:		
All other		Receive	Received by:		
Post approval re-review of	conditions of	_			
approval					
Property street address: 601 E. I	_ane St, Ralei	gh NC 276	301		
Historic district: Oakwood					
Historic property/Landmark name	(if applicable): Oo	den-Klein	House		
Owner name: Robin & Kimber	ly Weitkamp				
Owner mailing address: 601 E Lane St, Raleigh NC 27601					
For applications that require review by the COA Committee (major work), provide addressed and stamped envelopes for owners for all properties with 100 feet on all sides of the property, as well as the property owner.					
Property Owner Name & A	Address	Pro	perty Owner Name & Address		

I understand that all major work applications that require review by the Raleigh Historic Development Commission's COA Committee must be submitted by 4 p.m. on the date of the application deadline; otherwise, consideration will be delayed until the following committee meeting. An incomplete application will not be accepted.

Will you be applying for rehabilitation tax credits for this project?	Office Use Only
	Type of work: 67,82,84
Did you consult with staff prior to filing the application? Yes No	
Yes No	

Design Guidelines: please cite the applicable sections of the design guidelines (www.rhdc.org).					
Section/Page	Topic	Brief description of work (attach additional sheets as needed).			
66	stairs and walkway	restore front stairs to original concrete as current wood rots regularly			
85	new windows	additional, style-matching windows in conditioned basement			

	•
Min on Monte Ammunual (office use on	sha)
Minor Work Approval (office use on	
Upon being signed and dated below by the Planning Director or designee, this a Certificate of Appropriateness. It is valid until	application becomes the Minor Work
Please post the enclosed placard form of the certificate as indicated at the botto Certificate shall not relieve the applicant, contractor, tenant, or property owner for City Code or any law. Minor Works are subject to an appeals period of 30 days	om of the card. Issuance of a Minor Work from obtaining any other permit required by
Signature (City of Raleigh) Cuit Morton	


This property is the owner's residence. We request approval for several changes that are all consistent and important for maximizing the functionality, safety and overall maintenance and use of the residence. The following elements are requested for approval:

- (1) Window addition to lower level of house which is fully bricked-in and which already contains existing windows on both sides of the house.
 - a. On street-facing (Elm Street) side of house, add two (2) wooden 45" tall x 31" wide, 6-over-6 pane windows located to replace an existing former door (with only plywood as siding currently) placed next to one another with trim separation between. These new windows will match in height and trim configuration to the existing 2 windows on this side of the house.









b. On the neighbor-facing side of the house, replace an existing 4-over-4 window (45" t x 21" wide), but which does not open (is a single pane of glass) with an window appropriate for egress. This window is the same design and size as the windows being installed on the other side of the house: wooden 45" x 31", 6-over-6 pane style. Window will be placed at the same height, but the opening for the current window width-extended toward the front of the house by removal of bricks.





Left: View from rear of house (near back porch). Window to be replaced is the one shown in this view. Right: View from near front of house (neighbor side, above)





Bricks removed from one side (left, in picture) to expand opening for new window.

New window dimensions: 45'' tall x 31'' wide interior, plus trim vertically-oriented wood construction window.

- (2) Entry walkway and steps. 02/17/22: Applicant amended request to repair poured concrete in kind no COA required
 - a. Concrete walkway is in complete disrepair. Replace with tumbled concrete pavers (to provide visual of cobblestone) at grade and with the same shape as current.
 - b. Removal of wooden steps (subject to rot as they are in exposed weather) and install of concrete steps. The house originally had concrete steps appropriate for the period and we wish to restore this for historic value and for elimination of rot issues. The existing, exposed concrete 'walls' on both sides of the stairs (concrete) will remain as-is.

