LEESVILLE COMMUNITY PARK

EXISTING CONDITIONS




LEESVILLE COMMUNITY PARK

SCHEMATIC DESIGN

SITE DETAILS

PROPOSED NEW PLAY EQUIPMENT

- REPLACE EXISTING PLAYGROUND MULCH WITH POURED-IN-PLACE SURFACING.
- EXPAND PLAY AREA & ADD AN ADDITIONAL PLAY STRUCTURE.
- INSTALL AN ADDITIONAL SHADE SAIL FOR PLAYGROUND EXPANSION.
- REPLACE EXISTING TEMPORARY RESTROOM WITH PERMANENT RESTROOM STRUCTURE.
- REDESIGN CIRCULATION FROM THE LIBRARY TO PLAYGROUND & TRAILS.
- PROVIDE A READING NOOK WITHIN THE CENTRAL PARKING LOT ISLAND WITH CHAPEL HILL GRIT SURFACING AND INFORMAL SEATING.





STRICKLAND ROAD NEIGHBORHOOD PARK

EXISTING CONDITIONS





STRICKLAND ROAD NEIGHBORHOOD PARK

SCHEMATIC DESIGN



