



TOP VIEW - DCDA WITH FIRE HYD

IF THE TAP IS TO A PUBLIC MAIN, A SERVICE VALVE MUST BE PLACED BEHIND THE RIGHT OF WAY PRIOR TO THE BFP. TWO POSSIBLE LOCATIONS ARE SHOWN.

SIDE VIEW - DCDA WITH VARIABLE ENDINGS

NOTES:
1. SEE GENERAL NOTES ON DETAIL W-38

CITY OF RALEIGH		
STANDARD DETAIL		
REVISIONS	DATE: 01/18/2025	NOT TO SCALE
TYPICAL DOUBLE CHECK VALVE AND DOUBLE CHECK DETECTOR ASSEMBLY		
W-37		