

CERTIFICATE OF APPROPRIATENESS PLACARD

for Raleigh Historic Resources

Project Description:

Remove utility chimney and satellite dish

314 E Cabarrus St

Address

Prince Hall

Historic District

Historic Property

COA-0162-2023

Certificate Number

12/18/2023

Date of Issue

6/18/2024

Expiration Date

This card must be kept posted in a location within public view until all phases of the described project are complete. The work must conform with the code of the City of Raleigh and laws of the state of North Carolina. When your project is complete, you are required to ask for a final zoning inspection in a historic district area. Telephone the RHDC office at 832-7238 and commission staff will coordinate the inspection with the inspections Department. If you do not call for this final inspection, your Certificate of Appropriateness is null and void.

Signature, Ein Motton Pugh

Raleigh Historic Development Commission

Pending the resolution of appeals, commencement of work is at your own risk.

Type or print the following:						
Applicant name: Dane Barnes						
Mailing address: 314 E Cabarrus St						
City: Raleigh	State: NC		Zip code: 27601			
Date: 11/28/2023		Daytime pho	ytime phone #: 3368169966			
Email address: danebarnes3@gmail.com						
Applicant signature:/s/ Dane Barnes						
Minor work (staff review) – one copy Major work (COA committee review) – ten copies Additions > 25% of building sq. footage New buildings Demolition of building or structure All other Post approval re-review of conditions of approval		File #: C Fee: Amount Receive	Office Use Only Transaction #: File #: COA-0162-2023 Fee: Amount paid: Received date: Received by:			
	bornio Ct					
Property street address: 314 E Ca	ibarrus St					
Historic district: Prince Hall Historic property/Landmark name (if applicable):						
Owner name: Dane Barnes						
Owner mailing address: 314 E Cabarrus St, Raleigh, NC 27601						
		,				
For applications that require review by the COA Committee (major work), provide addressed and stamped envelopes for owners for all properties with 100 feet on all sides of the property, as well as the property owner.						
Property Owner Name & A	Address	Prop	perty Owner Name & Address			

I understand that all major work applications that require review by the Raleigh Historic Development Commission's COA Committee must be submitted by 4 p.m. on the date of the application deadline; otherwise, consideration will be delayed until the following committee meeting. An incomplete application will not be accepted.

Will you be applying for rehabilitation tax credits for this project? Yes No			Office Use Only Type of work: 22	
Did you consult Yes No	with staff prior to	filing the application?		
Design	Guidelines: please d	ite the applicable sections of the d	esign guidelines (<u>www.rhdc.org</u>).	
Section/Page Topic		Brief description of work (attach additional sheets as needed).		
			arata primar karabi	
			tagada Najalina ja	
		Minor Work Approval (office use of	nly)	
	and dated below by to priateness. It is valid		application becomes the Minor Work	
Please post the en Certificate shall no	closed placard form of trelieve the applicant	of the certificate as indicated at the bot	tom of the card. Issuance of a Minor Work from obtaining any other permit required by s from the date of approval.	
Signature (City of I	Raleigh) Em I	Voeth Pungh	Date 12/18/2023	

Hi RHDC team (Erin and Colette),

My name is Dane Barnes, and I own 314 E Cabarrus St, Raleigh, NC 27601. We've been working hard to keep it in good shape to preserve the house.

Request to remove the chimney (to the roof level) and satellite dish

We've discovered that the chimney on the back side of the house is in danger of leaking, and the roofer recommends removing the chimney to the roof level to prevent water damage. I'd also like to remove the satellite dish on the roof.

Chimney is not a prominent feature of the house

In my opinion, the chimney is not a prominent feature of the house, and it is not very visible from the street. Please see the photos of the chimney from various perspectives (pages 2-6).

Chimney is in danger of leaking

We've discovered that the chimney on the back side of the house is in danger of leaking, and the roofer recommends removing the chimney to the roof level to prevent water damage. I'd also like to remove the satellite dish on the roof. Please see the photos of the chimney up close showing that it is prone to water damage/ leaking (pages 7-9).

Fireplace covered up in previous renovation

The fireplace for the chimney is not visible inside the house as it was covered over by drywall and cabinets in a previous inside renovation. Please see the photos of the chimney from inside the house (page 9).

Materials

If given permission to remove the chimney (to the roof level) and satellite dish, we will match the color and material of the new roof tiles with the existing roof tiles.

Thank you for your help and consideration.

Best wishes, Dane

Cell: 336.816.9966

Email: danebarnes3@gmail.com



Front of house from street: chimney is <u>not</u> visible




Left side of house from street: chimney not a prominent feature of the house. You can also see the satellite dish in this photo.



Right side of house from street: chimney is <u>not</u> visible



Further to the right side of house from street: chimney is barely visible and not a prominent feature




Back of house: chimney only visible from very back of yard at the fence







Chimney (right side): flashing is installed incorrectly and is prone to water damage



Inside the house, the chimney is not visible because it is completely covered by cabinets and drywall on all sides.



