



Project Area 4
Neuse Connector




Connector Trail Closed -
No Detour Available

No access to Neuse
Connector during
construction.

Connector Trail Closed - No
Detour Available



Legend

-  Connector Trail and Bridge
-  Unnamed tributary
-  Limits of Disturbance

0 25 50 Feet

(At original document size of 8.5x11)
1:1,800



Project Location Raleigh Wake County, NC Prepared by MMR on 2020-02-26 TR by ALC on 2020-02-26

Client/Project City of Raleigh Neuse Connector Stream Repairs

Figure No.

Title
Limits of Disturbance

Coordinate System: NAD 1983 StatePlane North Carolina FIPS 3200 Feet
Base Imagery: 2017 NCONEMAP Aerial Orthoimagery Layer

Disclaimer: This document has been prepared based on information provided by others as cited in the Notes section. Stantec has not verified the accuracy and/or completeness of this information and shall not be responsible for any errors or omissions which may be incorporated herein as a result. Stantec assumes no responsibility for data supplied in electronic format, and the recipient accepts full responsibility for verifying the accuracy and completeness of the data.

VA1728\active\17261001103_data_design\04_gis\mxd\Neuse_Connector\Neuse_Connector_directions.mxd Revised: 2020-03-17 By: muiz